

Inclusive and Welcoming Sports Facilities

Summary of audit findings

Top issues across reserves

The 20 issues across pavilions with the highest fail rates are as follows:


- 1. Are public toilets available on non-game days? (91% fail)
- 2. Is there signage advertising what time the building is open? (85% fail)
- 3. Is there a comfortable and private place to breastfeed? (74% fail)
- 4. Are there baby change facilities that both men and women can access? (70% fail)
- 5. Are there privacy screens to minimise sight lines into change rooms? (66% fail)
- 6. Are the switch heights accessible? (62% fail)
- 7. Are shower and toilet cubicles accessible? (49% fail)
- 8. Are paths and approaches inclusive of different modes of transport? (47% fail)
- 9. Are there designated accessible parking spaces? (45% fail)
- 10. Are shower and toilet cubicles [in change rooms] unisex? (40% fail)
- 11. Is there ramp access, with railing, to the building? (38% fail)
- 12. Are there individual and lockable shower cubicles for privacy? (36% fail)
- 13. Are sound absorbing materials in use? (34% fail)
- 14. Are there sanitary bins? (30% fail)
- 15. Are there hooks on the back of amenity doors/change benches in showers? (30% fail)
- 16. Are there separate change rooms for officials? (30% fail)
- 17. Are doors easy to open? (28% fail)
- 18. Is there a microwave to heat up baby food/milk? (28% fail)
- 19. Is the building entrance clearly visible/obvious? (26% fail)
- 20. Is signage generally at eye level? (23% fail)

The people most likely to be affected by these issues are:

- People with a disability;
- Women:
- Parents;
- Children; and
- Older people.

Criteria

Environment, access and approach








Italiano 9321 5483


普通话 9321 5485


Việt Ngữ 9321 5487





















Building exterior






















Building interior (general)






Language Assistالعربية9321 5480廣東話9321 5481










Building interior (change rooms)







Language Assist旧東京語9321 5480廣東話9321 5481

Ελληνικά 9321 5482 Italiano 9321 5483

普通话 9321 5485

Русский 9321 5486 Việt Ngữ 9321 5487


















Language Assist旧文识显9321 5480廣東話9321 5481


Ελληνικά 9321 5482 Italiano 9321 5483 한국어 9321 5484 普通话 9321 5485 Русский 9321 5486 Việt Ngữ 9321 5487

















Building interior (club rooms)

