

Street Tree Renewal Information – Oregon Close, Wheelers Hill

The table below lists the details of the trees to be removed at each location.

No	Location	Species	Condition Assessment
1.	3 Oregon Close	<i>Callistemon citrinus</i>	Declining tree, canopy stressed, history of wounds in trunk, splitting scaffold branches, <2 Years ULE*

*< 2 Years ULE - a useful life expectancy of less than two years



The table below lists the details of the locations to be planted in vacant sites.

Ref	Street Location
1.	10 Oregon Close

MAP - Removals, Replacements and Infill Planting

The map below details the removals and infill plantings. All other trees have been assessed as having more than 2 years useful life and will be retained.



Legend	
	New Tree To be planted
	Tree to be removed but not replaced